

CORNER HISTORY: Corner originally set on July 29, 1881 by H.B.Fatout with the following witnesses for Section 25-17-3, as per Washington Township Legal Survey Book 1, page 104 as follows: Sycamore 30N 3 ¾ degrees W 28 3/4; (1) Oak 15N 73 ½ W 12; Oak 12 N 8 ¼ E 12 S; Ash 10 S 4 ½ degree E 28 ½; (2) Hackberry 24 N 1 degree E 17; Hackberry 12N 65 ¾ degree E 14 1/2; Box elder 14 S 62 ½ degree E 39; Hackberry 20 S 34 ¼ degree E 48; (3) Sycamore 36N 20 ½ degree W 43; Buckeye 12 N 84 degree W 30; Mulberry 16 S 13 degree E 52, variation 4 degree per Fatout. Same page documented: February 27, 1885 survey by D.B. Hosbrook W corner of 25-17-3. No record found in the 'old' 3"x5" cards. Corner reference dated March 2, 1976 per Rick Miller called for a brass plug, reference also was made that this information came from October 29, 1962 brass plug. Corner reference dated April 18, 1996 by Kiste recorded a MCSO capped rebar found at this location. Corner reference dated September 22, 2008 by Wilcoxen set a Harrison marker during re-surfacing project. Section ties are as follows:

REF.	DISTANCE	DESCRIPTION
1. 2. 3.	57.07' 88.01' 46.64'	SF corner of concrete signal box  Mag nail w/bw S FM.Siren PwP no# 24"up  Mag nail w/bw NF PwP#111-267A 12"up
4. 5.	54.36' 48.65'	Cut 'x' NW bolt of steel light pole base  Cut 'x' SW bolt of steel light pole base